

## Product Recall Notice

### IC-A220 (#71) TSO


Thank you for your continued patronage of Icom products.

We have identified a potential issue affecting certain **IC-A220 (#71) TSO** units. As a precautionary measure, we have decided to recall all affected units. We sincerely apologize for any inconvenience this may cause.

#### Affected Product

- **Product name:** IC-A220 (#71) TSO
- **Affected units:** All IC-A220 (#71) TSO units sold to date
- **Affected Serial Numbers :** TA711001~TA711371  
TA711381~TA711390

The Serial Number label is placed to the left of three labels on the top of the Chassis.



## **Description of the Issue**

The following issue has been confirmed under specific operating conditions:

- When the IC-A220 (#71) TSO is operated with a **24V power supply**, the unit may fail to power on. Once powered on, the unit does not unintentionally power off.
- When operated with a **12V power supply**, this issue does not occur.

## **Countermeasure**

To address this issue, we will carry out a **performance improvement to expand the operating voltage margin**.

## **Customer Action**

Customers using the affected IC-A220 (#71) TSO model are kindly requested to **contact the retailer from whom the product was purchased** for further instructions regarding this recall.

## **Apology**

We deeply regret any inconvenience or concern this issue may have caused to our customers and business partners. We appreciate your understanding and cooperation.